


Project Background

- Original sewer main ~80 years old
- History of bypass events directly into lake
- Difficult maintenance
- Lake erosion exposed pipe potential
- Located in residential lakefront yards


























































HJ0 Josh please put a short caption or detail of what is happening in the video


Hannah Johnson, 2023-05-02T17:03:30.542














Real People, Real Feedback

"THANK YOU for all you and your crew did to make our son's wedding day a success! I must say that the smaller renovation projects of the cottages next door have caused significantly more inconvenience than your very large project."



"We have been very pleased with the work of Bolton & Menk on all of our projects. They have provided quality design along with a dedicated staff that provides great communication to staff and elected and appointed officials all while keeping the project on time.

"Bolton & Menk's
communication with property
owners during construction
has been exceptional. I
typically only hear complaints
while projects are being
completed, however, I have
received numerous positive
comments from the public
regarding their work."





Thank you!

Josh Pope PE, ENV SP, LEED AP BD+C Principal Engineer



